NUC7ixBN HDMI FW Update Release Notes-Version 1.77.93

1.77.93

1. Modify HDMITX Gain to fix EMI issue and SI CTS.

1.77

1. Fixed display noise at 4K@30Hz in LS re-timer mode.
2. Modify CMDB LS-mode from redrivermode to retimer mode.

1.76

1. Keep Aux FIFO zone Isr enabled so that InfoFrame overwrite to DPCD 5C0h is still allowed in sink disconnected state.
2. Modify CMDB LS-mode from retimer mode to redriver mode.

1.75

1. Fixed occasional link training failure on Intel Linux driver with sleep/wakeup test utility.

1.74

1. Filter out temporal incorrect 3D timing by checking MSA parameters.
2. Filter out illegal VSC SDP data in case wrong 3D config parameters are overridden.